

TEST REPORT

Swab Test - Bacteria Count

Date of issue : 09-06-2018
Page 1 of 3

Castco LRN: MB0180531-1

Sample details as supplied by customer:-

Customer: Top Excel (Hong Kong) Ltd.

Address: Room 1504, 15/F., Ricky Centre, 36 Chong Yip Street, Kwun Tong, Kowloon

Job Title: Bacteria Swab Test: "Two Year after Application of Marusyo Sangyo M-Clean Photocatalyst Coating at Civil Aviation Department Headquarter

Date Sampled: 31-05-2018

Contract No.: -

Customer Ref. No.: -

Sampling Certificate attached? Yes; Ref.No.: -- / No

Laboratory Test Result(s):-

Date of sample received: 31-05-2018

Test period: 31-05 to 02-06-2018

Received Condition: Chilled

Reference standard of Test Method

US FDA, BAM Online, Ch. 3, 2001.

Remark(s):

1. Countable Range: 15-150 CFU, TNTC: Too numerous to count, *:Contain Spreader, #: Estimated Count.

Checked by :


Lau Hiu Ching
Microbiologist

Certified by:


Horasis Leung
Technical Manager

TEST REPORT

Swab Test - Bacteria Count

Date of issue : 09-06-2018
Page 2 of 3

Castco LRN: MB0180531-1

Related to Castco LRN	Loaction No.	Client ID	Total Bacterial Count (CFU/Swab)
MB0180531-01-01	1	1/F, 121, 木門扶手(右)	<10
MB0180531-01-02	2	1/F, ANC(125), 木門扶手(右)	10
MB0180531-01-03	3	1/F, ANC(125), 125B房門扶手(外)	<10
MB0180531-01-04	4	1/F, 走廊往125, 木門扶手(左)	<10
MB0180531-01-05	5	1/F, Locker Room(133), 木門扶手(前 外)	<10
MB0180531-01-06	6	1/F, Locker Room(133), 更衣室(三格) 門柄(外)	<10
MB0180531-01-07	7	1/F, Locker Room(133), 更衣室(三格) 門柄(外)	<10
MB0180531-01-08	8	1/F, 女廁B近133, 外門柄(右邊第三 格)	<10
MB0180531-01-09	9	1/F, WKCC(106), 木門柄(右)	<10
MB0180531-01-10	10	1/F, WKCC(107), 木門柄(右)	<10
MB0180531-01-11	11	1/F, WKCC(111), 木門柄(右)	40
MB0180531-01-12	12	1/F, ATCC(117), 往外圍門柄(左)	<10
MB0180531-01-13	13	1/F, 男廁A近117, 外門柄(右格)	10
MB0180531-01-14	14	1/F, 女廁A近117, 外門柄(右格)	<10
MB0180531-01-15	15	1/F, ATCC(117), 往121門柄(右)	<10
MB0180531-01-16	16	1/F, 男廁B近133, 外門柄(最右格)	<10
MB0180531-01-17	17	G/F, 18 & 19號升降機大堂, 右控制板	40
MB0180531-01-18	18	G/F, 大堂, 扶手(落樓梯右)	<10
MB0180531-01-19	19	G/F, 大堂, 上1/F 扶手(落斜左)	10
MB0180531-01-20	20	G/F, 大堂, 1/F 往Office(轉彎落斜左, RM050對面)	20
MB0180531-01-21	21	G/F, 女廁, 外門柄(最右格)	<10
MB0180531-01-22	22	G/F, 男廁, 外門柄(最左格)	10
MB0180531-01-23	23	2/F, 升降機大堂, 往Office外門柄(左)	<10
MB0180531-01-24	24	2/F, RCC, 232, 外門柄(左)	<10
MB0180531-01-25	25	2/F, 女廁A近232, 外門柄(左排最右)	<10
MB0180531-01-26	26	2/F, 男廁A近232, 外門柄(最左格)	<10
MB0180531-01-27	27	2/F, AIMC(205), 205E, 外門柄	<10

Form No. ENV AIR_T1 dd 16/11/2008

TEST REPORT

Swab Test - Bacteria Count

Date of issue : 09-06-2018
Page 3 of 3

Castco LRN: MB0180531-1

MB0180531-01-28	28	2/F, AIMC(205), 往Office木門, 內門柄 (右)	<10
MB0180531-01-29	29	2/F, 男廁B, 教育徑, 外門柄	20
MB0180531-01-30	30	2/F, 女廁B, 教育徑, 外門柄	<10
MB0180531-01-31	31	2/F, 20 & 21號升降機大堂, 控制板	10
MB0180531-01-32	32	G/F, 20 & 21號升降機大堂, 控制板	<10
MB0180531-01-33	33	2/F, 18 & 19號升降機大堂門(外左)	<10
MB0180531-01-34	34	2/F, 升降機大堂, 往OB, 外門柄(右)	<10
MB0180531-01-35	35	3/F, 18號升降機大堂, 控制板	<10
MB0180531-01-36	36	3/F, Common area, 往lift lobby玻璃門, 外門柄(左)	<10
MB0180531-01-37	37	3/F, Common area, 往lift lobby玻璃門, 外門柄(右)	<10
MB0180531-01-38	38	3/F, 升降機大堂, 往OB, 外門柄(右)	<10
MB0180531-01-39	39	3/F, 308, 廁所A, 外門柄(左)	<10
MB0180531-01-40	40	3/F, 320, 殘廁A, 內門柄	<10
MB0180531-01-41	41	320, 房門外	<10
MB0180531-01-42	42	3/F, 319, 319B, 外門柄	<10
MB0180531-01-43	43	3/F, 319, 319G, 外門柄	<10
MB0180531-01-44	44	3/F, 318, 318D, 外門柄	<10
MB0180531-01-45	45	3/F, 317, 317C, 外門柄	20
MB0180531-01-46	46	3/F, 317, 睡房往浴室, 外門柄	<10
MB0180531-01-47	47	3/F, 316, 316F, 外門柄	<10
MB0180531-01-48	48	3/F, 315, 315B, 外門柄	<10
MB0180531-01-49	49	3/F, 315, 廁所B, 外門柄	<10
MB0180531-01-50	50	3/F, Common area, 往311木門, 外門柄	<10
MB0180531-01-51	51	3/F, Common area, 往312木門, 外門柄	<10
MB0180531-01-52	52	2/F, 男廁大門(外)	<10
MB0180531-01-53	53	2/F, 女廁大門(外)	<10
MB0180531-01-54	54	2/F, 18 & 19號升降機大堂門(外右)	<10

End of Report